

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE ER REGULATORY CONTACT RECORD

Date/Time December 10, 2002/ 11 00 am

Site Contact(s) Hanna Marschall, Reginald Tyler
Phone (303) 966-4058, (303) 966-5927

Regulatory Contact Elizabeth Pottorff
Phone (303) 692-3429

Agency CDPHE

Purpose of Contact Location of additional soil samples at Building 335

Discussion

Two (2) under building sample locations, as described in the IASAP Addendum #1A-02-01 for IHSS Group 300-1, were relocated outside the slab perimeter due to the logistics of positioning the geoprobe with the facility structure in place. As discussed with and agreed to by David Kruchek and Elizabeth Pottorff, CDPHE and Reg Tyler, DOE, after removal of the concrete slabs and the sump at the site of B335, one soil sample will be taken at each of the three following locations: (1) under the older concrete slab (east section) of the building near the building drains, (2) under the new concrete slab (west section), near the building drains, and (3) under the sump. The samples will be analyzed for volatile organic compounds (VOC) and metals.

Contact Record Prepared By Hanna Z. Marschall

Required Distribution

S Bell, RFFO	D Mayo, K-H RISS
L Brooks, K-H ESS	J Mead, K-H ESS
L Butler, K-H RISS	S Nesta, K-H RISS
C Deck, K-H Legal	K North, K-H ESS
R DiSalvo, RFFO	T Rehder, USEPA
S Gunderson, CDPHE	D Shelton, K-H
J Legare, RFFO	C Spreng, CDPHE
D Kruchek, CDPHE	R Tyler, RFFO

Additional Distribution

(choose names as applicable)

M Broussard, K-H RISS
C Freiboth, K-H RISS
G Kleeman, USEPA
S Serreze, K-H RISS
L Norland, K-H RISS
A Primrose, K-H RISS
E Pottorff, CDPHE
D Foss, K-H RISS
G Kelly, K-H RISS
H Marschall, K-H RISS
N Castaneda, RFFO
S Surovchak, RFFO



Contact Record 6/20/02
Rev 6/20/02

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE

Page 1 of 1

CEX-105-01

ADMIN RECORD

1A-A-001213